

K f 3 0 4

: K T - V A 0 4



K F .

		()			
K F 2 5	4 0 mm	2 3 mm	3 5 0	1 5 . 5 mm	3 0 4 +
K F 4 0	5 5 mm	2 0 mm		1 5 . 5 mm	
K F 5 0	7 5 mm	3 4 mm		1 6 mm	