


1 2 0 0

: K T - 1 2 M



K T - 1 2 M : P I D
1 2 0 0 ° C

K T - 1 2 M / K T - 1 2 M P r o	
1 2 0 0	
1 1 0 0	
(,)	()
C r 2 A l 2 M o 2	
0 - 3 0 / m i n	
K	
P I D (K T - 1 2 M) / 7	P I D (K T - 1 2 M P r o)
± 1	
± 5	
A C 1 1 0 - 2 2 0 V , 5 0 / 6 0 H Z	

(mm) WxDxH	(L)	(mm) WxDxH	(L)
100x100x100	1	300x300x400	36
150x150x150	3.4	400x400x400	64
150x150x200	4.5	500x500x500	125
200x200x200	8	600x600x600	216
200x200x300	12	800x800x800	512

--	--	--

1 (K T - 1 2 M K T - 1 2 M F 1

2	/	1
3		1
4		1
5		1