

1 7 0 0

: K T - 1 7 A



K T - 1 7 A
1 7 0 0 ° C

:

. ,

!

	K T - 1 7 A
	1 7 0 0
	1 6 0 0
	- 0 . 1 M p a
	0 - 2 0 / m i n
	B
	P I D / P I D
	± 1
	± 5
	A C 1 1 0 - 2 2 0 V , 5 0 / 6 0 H Z

(mm)	(L)	(mm)	(L)
1 0 0 x 1 0 0 x 1 0 0	1	3 0 0 x 3 0 0 x 4 0 0	3 6
1 2 0 x 1 2 0 x 1 3 0	2	4 0 0 x 4 0 0 x 4 0 0	6 4
1 5 0 x 1 5 0 x 2 0 0	4 . 5	5 0 0 x 5 0 0 x 5 0 0	1 2 5
2 0 0 x 2 0 0 x 2 0 0	8	6 0 0 x 6 0 0 x 6 0 0	2 1 6
2 0 0 x 2 0 0 x 3 0 0	1 2	8 0 0 x 8 0 0 x 8 0 0	5 1 2

--	--	--

1	F u r n a c e	1
2		1
3		1
4		1
5		1