

K f I s o

: K T - V A 1 2



K F / I S O

3 0 4 / 3 1 6

V i t o n / E P D M

K F I S O

!

	A	B	C	D
I S O 6 3	9 5 m m	1 2 m m	7 0 m m	9 0 m m
I S O 8 0	1 1 0 m m	1 2 m m	8 3 m m	1 0 5 m m
I S O 1 0 0	1 3 0 m m	1 2 m m	1 0 2 m m	1 2 5 m m
I S O 1 2 5	1 5 5 m m	1 2 m m	1 2 7 m m	1 5 0 m m
I S O 1 6 0	1 8 0 m m	1 2 m m	1 5 3 m m	1 7 5 m m
I S O 2 0 0	2 4 0 m m	1 2 m m	2 1 3 m m	2 3 5 m m
I S O 2 5 0	2 9 0 m m	1 2 m m	2 6 1 m m	2 8 5 m m
I S O 3 2 0	3 7 0 m m	1 7 m m	3 1 8 m m	3 6 5 m m
I S O 4 0 0	4 5 0 m m	1 7 m m	4 0 0 m m	4 4 5 m m
I S O 5 0 0	5 5 0 m m	1 7 m m	5 0 1 m m	5 4 5 m m
I S O 6 3 0	6 9 0 m m	2 2 m m	6 5 1 m m	6 8 5 m m

	A	B
K F 1 0	1 2 . 2 m m	3 0 m m
K F 1 6	1 7 . 2 m m	3 0 m m
K F 2 5	2 6 . 2 m m	4 0 m m
K F 4 0	4 1 . 2 m m	5 5 m m
K F 5 0	5 2 . 2 m m	7 5 m m
K F 6 3	7 0 m m	8 7 m m
K F 8 0	8 3 m m	1 1 4 m m
K F 1 0 0	1 0 2 m m	1 3 4 m m
K F 1 6 0	1 5 3 m m	1 9 0 m m

	A	B	C * n o	P . C . D
CF 1 6	3 4 mm	7 . 5 mm	4 . 4 * 6	2 6 . 9 mm
CF 2 5	5 4 mm	1 0 . 5 mm	6 . 6 * 6	4 3 mm
CF 3 5	7 0 mm	1 2 . 7 mm	6 . 7 * 6	5 8 . 7 mm
CF 5 0	8 6 mm	1 6 mm	8 . 4 * 8	7 2 . 4 mm
CF 6 3	1 1 4 mm	1 8 mm	8 . 4 * 8	9 2 . 1 mm
CF 8 0	1 3 0 mm	1 8 mm	8 . 4 * 1 6	1 1 0 mm
CF 1 0 0	1 5 2 mm	2 0 mm	8 . 4 * 1 6	1 3 0 . 3 mm
CF 1 5 0	2 0 2 mm	2 2 mm	8 . 4 * 2 0	1 8 1 mm
CF 2 0 0	2 5 3 mm	2 4 . 5 mm	8 . 4 * 2 4	2 3 1 . 8 mm
CF 2 5 0	3 0 5 mm	2 6 mm	8 . 4 * 3 2	2 8 4 mm
CF 3 0 0	3 6 8 mm	2 8 . 5 mm	1 0 . 8 * 3 6	3 3 8 . 1 mm
CF 3 5 0	4 1 9 . 1 mm	2 8 . 5 mm	1 0 . 8 * 3 6	3 8 8 . 9 mm