

: K T - V F



1 7 0 0 ° C

	K T - V F 1 2 / K T - V F 1 7		
	1 2 0 0 ° C / 1 7 0 0		
	1 1 0 0 ° C / 1 6 0 0		
	C r 2 A l 2 M o 2	/	(M o S i 2)
	0 - 2 0 / ()		
	K / B		
	P L C	P I D	
	± 1		
	± 5		
	A C 1 1 0 - 4 4 0 V , 5 0 / 6 0 H Z ()		

()			
(mm) (D x W x H)	(L)	(mm) (D x W x H)	(L)
1 0 0 x 1 0 0 x 1 0 0	1	4 0 0 x 4 0 0 x 5 0 0	8 0
1 5 0 x 1 5 0 x 2 0 0	4 . 5	5 0 0 x 5 0 0 x 6 0 0	1 2 5
2 0 0 x 2 0 0 x 3 0 0	1 2	6 0 0 x 6 0 0 x 7 0 0	2 5 3
3 0 0 x 3 0 0 x 4 0 0	3 6	8 0 0 x 8 0 0 x 8 0 0	5 1 2